



- 1 Interior improvements in all public area:
New floor, wall and ceiling finishes;
New energy efficient LED lighting and lighting control systems
New wayfinding and collection signage
Wi-Fi connection throughout
Energy and performance Improvements including Improved roof insulation; replace window glazing with insulated glazing
Fire-Alarm system Electrical system upgrades to meet current demands
- 2 Exterior improvements:
Paint/refinish entire exterior wall, window frames, soffits
Repoint and clean brick
Clean and reinstall historic signage
New energy efficient building lighting
- 3 Reading Room
New carpet; acoustical wood ceiling
New service desk and furniture
A fireplace and seating area
Skylights
New and refinished library shelving
(12) Public Computers
(2) Self-service check-out stations
- 4 Community Room
Wood flooring; acoustical wood ceiling
Glass doors to the new patio
Large format TV; sound and presentation technology
Assisted Listening system
- 5 Kitchen
Reduced size to meet need
New storage closet
- 6 New multi-occupant restrooms
Tile floor and wall finishes
Provision for access from outside
- 7 Study Rooms/Area
(3) new study rooms (~300SF Building addition)
Carpet flooring; Acoustical wood ceiling
Windows to the park
Refinished Meeting Room
(1) Study/office space
Interior sliding glass doors
- 8 Staff Area
New floor, wall and ceiling finishes
New energy efficient LED lighting
New energy efficient, insulated glass windows
- 9 Staff Lounge
New floor, wall and ceiling finishes
New handicapped - accessible kitchenette counter
- 10 Staff Restroom
Combine two small/old restrooms into one
- 11 Mechanical Room
New high-efficiency HVAC systems serving the reading rooms and Community Room
- 12 Server Room upgrades (at basement)

SCALE 1/8" = 1' - 0"







